

ATTORNEY'S DOCKET:  
062891.0363

PATENT NO:  
6,920,156 B1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Manchester, et al.  
U.S. Patent No.: 6,920,156 B1  
Issue Date: July 19, 2005  
Serial No.: 09/452,753  
Filing Date: December 1, 1999  
Title: *Method and System for Transporting Synchronous and Asynchronous Traffic on a Synchronous Bus of a Telecommunications Node*

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450


Dear Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**UNDER 37 CFR § 1.322**

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The errors involved are believed to be Patent Office errors, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that significant errors are present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,  
BAKER BOTTS L.L.P.  
Attorneys for Applicant

  
Barton E. Showalter  
Reg. No. 38,302

Date: Aug 31, 2006  
BAKER BOTTS L.L.P.  
2001 Ross Avenue, Suite 600  
Dallas, Texas 75201-2980  
Phone: (214) 953-6509

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Patent No.: 6,920,156 B1  
Dated: July 19, 2005  
Inventor(s): Manchester, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 33, Line 66, Claim 1, after "connection," insert -- a current channel associated signaling (CAS) value for the DS-0 connection located within --.

Column 33, Line 67, Claim 1, after "channels" delete "comprising a current channel associated signaling (CAS) value for the DS-0 connection".

Column 34, Line 50, Claim 12, after "to" delete ";" and insert -- : --.

Column 34, Line 54, Claim 12, after "frame," insert -- a current channel associated signaling (CAS) value for a DS-0 connection location within --.

Column 34, Line 55, Claim 12, after "channels" delete "comprising a current channel associated signaling (CAS) value for a DS-0 connection".

Column 35, Line 29, Claim 16, after "channels," insert -- comprising a current channel associated signaling (CAS) value for the DS-0 connection located within --.

Column 35, Line 30, Claim 16, after "channels" delete "comprising a current channel associated signaling (CAS) value for the DS-0 connection".

**Mailing Address of Sender:**

Baker Botts L.L.P.  
2001 Ross Avenue, Suite 600  
Dallas, Texas 75201-2980

**Patent No.** 6,907,004 B1

Form PTO-1050

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Patent No.: 6,920,156 B1  
Dated: July 19, 2005  
Inventor(s): Manchester, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 35, Line 37, Claim 16, after "and the" delete "AIM" and insert -- ATM --.  
Column 36, Line 5, Claim 22, after "connection," insert -- a current channel associated signaling (CAS) value for the DS-0 connection located within --.  
Column 36, Line 6, Claim 22, after "channels" delete "comprising a current channel associated signaling (CAS) value for the DS-0 connection".  
Column 37, Line 7, Claim 28, after "channels," insert -- current channel associated signaling (CAS) value for the DS-0 connection located within --.  
Column 37, Line 9, Claim 28, after "channels" delete "comprising a current channel associated signaling (CAS) value for the DS-0 connection".  
Column 38, Line 10, Claim 33, after "message" delete "fire" and insert -- free --.

**Mailing Address of Sender:**  
Baker Botts L.L.P.  
2001 Ross Avenue, Suite 600  
Dallas, Texas 75201-2980

**Patent No.** 6,907,004 B1

Form PTO-1050